


BGJWSC Sanitary Sewer Manhole Inspection Form

SID: 4044 0100
 Northing Coord:
 Easting Coord:
 Address/Intersection: 256 STANTON CORN

Rim Elev:
 Grade Elev:
 Invert "A" Down Dist: 5.55
 Invert "A" Pipe Dia: Ø 12
 Invert "A" Pipe Type: PVC
 Invert "A" Clock Position: 6
 Invert "B" Down Dist: 5.5
 Invert "B" Pipe Dia: 8
 Invert "B" Pipe Type: PVC
 Invert "B" Clock Position: 9
 Invert "C" Down Dist: 5.55
 Invert "C" Pipe Dia: 8
 Invert "C" Pipe Type: PVC
 Invert "C" Clock Position: 3



Force Main Code:
 Drop MH Code:
 Free Drop MH Code:
 Frame Dia: 25 1/2
 Frame & Cover Problem: Yes No
 Manhole Security Problem: Yes No
 MH Diameter: 48
 Surface Ponding Area: Yes No
 Inflow Protector Installed: Yes No
 Invert Ponding: Yes No

Structure Material: precast brick lined coated plastic
 Infiltration Rating: 1=acceptable 2=minor 3=moderate 4=significant 5=collapse imminent
 Inflow Rating: 1=acceptable 2=minor 3=moderate 4=significant 5=collapse imminent
 Root Rating: 1=acceptable 2=minor 3=moderate 4=significant 5=collapse imminent
 Corrosion Rating: 1=acceptable 2=minor 3=moderate 4=significant 5=collapse imminent
 H₂S Vapor PPM: 0 - 10 ppm 2 = 11 - 50 ppm 3 = 51 - 100 ppm 4= 101 - 1,000 ppm 5 = >1,000 ppm
 Grease Rating: 1=acceptable 2=minor 3=moderate 4=significant 5=collapse imminent
 Debris Rating: 1=acceptable 2=minor 3=moderate 4=significant 5=collapse imminent
 Location: Road ROW Highway Secondary Road Residential Road Easement/ROW
 Surface: Asphalt Concrete Grassed Area Landscaped Yard Marshland Ditch
 Obstructions: Yes No

Remarks: Layout All PIPES INSIDE MH