

# Water Tank Inspection for: Brunswick - Glynn County Joint Water & Sewer Commission Mall Tank 500,000 Galon Elevated

Inspection Date: 2/21/2022 10:00:00 AM

Inspector: Tom Chapman(251-654-5414)

\* The tank exterior hs peeling coatings all over and it is recommended that the tank exterior get blasted to bare metal

The tank interior has rust spots all around and it is recommeded theat the tank interior get blasted to bare metal and over coated.

The tank interior dry areas have peeling coatings on the platforms and have rust spots on the shell. It is recommended that the tank interior dry area get blasted to bare metal and over coated.

| Tank Height:                                | 135 ft. to Overflow |
|---|---------------------|
| Year Tank Built:                            | 1987                |
| Tank Foundation:                            | Good Condition      |
| Anchor Bolts:                               | Surface rusting     |
| Exterior Paint:                             | Urethane            |
| Interior Paint:                             | Ероху               |
| Tank Legs:                                  | Tank Exterior       |
| Tank Riser:                                 | Rust spots all over |
| Tank Bowl:                                  | Rust spots all over |
| Tank Shell Wall:                            | Rust spots all over |
| Tank Roof:                                  | Rust spots all over |
| Tank Riser Rods:                            | n/a                 |
| Tank Wind Rods:                             | n/a                 |
| Inspect the tank's balconies and handrails: | n/a                 |
| Does the Tank Have Lead Paint:              | No                  |

| Exterior Coatings Adhesion:             | Poor  |  |  |  |  |  |  |  |
|---|---|--|--|--|--|--|--|--|
| Average Support Tower DFT(mils):        | 30  |  |  |  |  |  |  |  |
| Average Tank Sidewall DFT(mils):        | 27  |  |  |  |  |  |  |  |
| Average Tank Top DFT(mils):             | 32  |  |  |  |  |  |  |  |
|   | Tank Interior   |  |  |  |  |  |  |  |
| Interior ceiling Beams:                 | n/a   |  |  |  |  |  |  |  |
| Interior ceiling:                       | Surface rust occuring   |  |  |  |  |  |  |  |
| Interior Side Walls:                    | 27 32  Tank Interior n/a  |  |  |  |  |  |  |  |
| Interior Floor:                         | Tank was full for this inspection   |  |  |  |  |  |  |  |
| Interior Riser:                         | n/a   |  |  |  |  |  |  |  |
| Inspection of sanitary conditions:      | Tank was full for this inspection   |  |  |  |  |  |  |  |
| Average Tank Interior DFT(mils):        | 25  |  |  |  |  |  |  |  |
|   | Tank Dry Interior   |  |  |  |  |  |  |  |
| Dry Area Condition:                     | Rust spots all over   |  |  |  |  |  |  |  |
| Dry Area Ladder:                        |   |  |  |  |  |  |  |  |
| Dry Area Average DFT:                   | 12  |  |  |  |  |  |  |  |
|   | Tank Accessories  |  |  |  |  |  |  |  |
| Riser Manway:                           |   |  |  |  |  |  |  |  |
| Top Hatch:                              | Section Loss occuring   |  |  |  |  |  |  |  |
| Top Vent:                               | Tank was full for this inspection  n/a  Tank was full for this inspection  25  Tank Dry Interior  Rust spots all over  Peeling coatings  12  Tank Accessories  n/a  Section Loss occuring  Good Condition  n/a  n/a  Minimal Rust Spots   |  |  |  |  |  |  |  |
| Exterior Ladder:                        | n/a   |  |  |  |  |  |  |  |
| Knuckle Ladder:                         | n/a   |  |  |  |  |  |  |  |
| Interior Bowl Ladder                    | Minimal Rust Spots  |  |  |  |  |  |  |  |
| Interior Riser Ladder:                  | n/a   |  |  |  |  |  |  |  |
| Inspection of OSHA-related accessories: | Main Ladder has safety climb  |  |  |  |  |  |  |  |
| Inspection of cathodic protection:      | Tank Interior  n/a  Surface rust occuring  Surface rust occuring  Tank was full for this inspection  n/a  Tank was full for this inspection  25  Tank Dry Interior  Rust spots all over  Peeling coatings  12  Tank Accessories  n/a  Section Loss occuring  Good Condition  n/a  n/a  Minimal Rust Spots  n/a  Main Ladder has safety climb  No cathodic protection on tank  Flap and screen in place  In Place and Locked |  |  |  |  |  |  |  |
| Overflow Protection:                    | Flap and screen in place  |  |  |  |  |  |  |  |
| Exterior Fence:                         | In Place and Locked   |  |  |  |  |  |  |  |
| Ladder Gate:                            | Pedesphere Tank with locking bottom door  |  |  |  |  |  |  |  |
| Top Hatch:                              | n/a  Minimal Rust Spots  n/a  Main Ladder has safety climb  No cathodic protection on tank  Flap and screen in place  In Place and Locked   |  |  |  |  |  |  |  |

See pictures below for more information

Ed Chapman

**Chapman Technical Services, LLC** 

5858 Vaughn Dr E Satsuma, AL 36572 251-442-5911


























































































Pace Analytical Services, LLC 4320 Midmost Dr Mobile, AL 36609

251-344-9106



March 04, 2022

Ed Chapman Chapman Technical Services 5556 7th St. Satsuma, AL 36572

RE: Project: Brunswick GA 2/28/22

Pace Project No.: 20236149

# Dear Ed Chapman:

Enclosed are the analytical results for sample(s) received by the laboratory on February 28, 2022. The results relate only to the samples included in this report.

The test results provided in this final report were generated by each of the following laboratories within the Pace Network:

• Pace Analytical Services - New Orleans

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Savannah Wallace savannah.wallace@pacelabs.com 251-344-9106

Sh Whate

Project Manager

Enclosures





# **CERTIFICATIONS**

Project: Brunswick GA 2/28/22

Pace Project No.: 20236149

**Pace Analytical Services New Orleans** 

Florida Department of Health (NELAC): E87595 Illinois Environmental Protection Agency: 0025721 Kansas Department of Health and Environment (NELAC):

E-10266

Louisiana Dept. of Environmental Quality (NELAC/LELAP):

02006

Texas Commission on Env. Quality (NELAC):

T104704405-09-TX

U.S. Dept. of Agriculture Foreign Soil Import: P330-10-

00119



# **SAMPLE SUMMARY**

Project: Brunswick GA 2/28/22

Pace Project No.: 20236149

| Lab ID      | Sample ID  | Matrix | Date Collected | Date Received  |  |
|-------------|------------|--------|----------------|----------------|--|
| 20236149001 | Oglethorpe | Solid  | 02/24/22 10:00 | 02/28/22 14:12 |  |
| 20236149002 | Mall       | Solid  | 02/24/22 11:00 | 02/28/22 14:12 |  |



# **SAMPLE ANALYTE COUNT**

Project: Brunswick GA 2/28/22

Pace Project No.: 20236149

| Lab ID      | •          | Method   | Analysts | Analytes<br>Reported |  |  |  |
|-------------|------------|----------|----------|----------------------|--|--|--|
| 20236149001 | Oglethorpe | EPA 6010 | AJS      | 1                    |  |  |  |
| 20236149002 | Mall       | EPA 6010 | AJS      | 1                    |  |  |  |

PASI-N = Pace Analytical Services - New Orleans



#### **ANALYTICAL RESULTS**

Project: Brunswick GA 2/28/22

Pace Project No.: 20236149

Date: 03/04/2022 02:04 PM

Lab ID: 20236149001 Collected: 02/24/22 10:00 Received: 02/28/22 14:12 Matrix: Solid Sample: Oglethorpe Results reported on a "wet-weight" basis **Parameters** Results Units Report Limit DF Prepared Analyzed CAS No. Qual Analytical Method: EPA 6010 Preparation Method: EPA 3050 6010 Metals, Total Pace Analytical Services - New Orleans ND 03/03/22 09:06 03/03/22 18:05 7439-92-1 Lead mg/kg 4.1 10 D3 Sample: Mall Lab ID: 20236149002 Collected: 02/24/22 11:00 Received: 02/28/22 14:12 Matrix: Solid Results reported on a "wet-weight" basis **Parameters** Results Units Report Limit DF Prepared Analyzed CAS No. Qual 6010 Metals, Total Analytical Method: EPA 6010 Preparation Method: EPA 3050 Pace Analytical Services - New Orleans 4.8 Lead mg/kg 4.6 10 03/03/22 09:06 03/03/22 18:09 7439-92-1 D3



#### **QUALITY CONTROL DATA**

Project: Brunswick GA 2/28/22

Pace Project No.: 20236149

QC Batch: 249087 QC Batch Method: EPA 3050

Date: 03/04/2022 02:04 PM

Analysis Method: EPA 6010
Analysis Description: 6010 MET

Laboratory:

Pace Analytical Services - New Orleans

Associated Lab Samples: 20236149001, 20236149002

METHOD BLANK: 1183162 Matrix: Solid

Associated Lab Samples: 20236149001, 20236149002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Lead mg/kg ND 0.50 03/03/22 14:18

LABORATORY CONTROL SAMPLE: 1183163

Spike LCS LCS % Rec Conc. Result % Rec Limits Qualifiers Parameter Units Lead 100 101 101 85-115 mg/kg

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 1183164 1183165

MS MSD

20235990001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Conc. Result Result % Rec % Rec **RPD** RPD Qual Result Conc. Limits Lead mg/kg 0.79 58.8 54.9 57.9 50.7 97 91 80-120 13 20

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



#### **QUALIFIERS**

Project: Brunswick GA 2/28/22

Pace Project No.: 20236149

#### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to dilution of the sample aliquot.

ND - Not Detected at or above adjusted reporting limit.

TNTC - Too Numerous To Count

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PQL - Practical Quantitation Limit.

RL - Reporting Limit - The lowest concentration value that meets project requirements for quantitative data with known precision and bias for a specific analyte in a specific matrix.

S - Surrogate

1,2-Diphenylhydrazine decomposes to and cannot be separated from Azobenzene using Method 8270. The result for each analyte is a combined concentration.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

**DUP - Sample Duplicate** 

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Reported results are not rounded until the final step prior to reporting. Therefore, calculated parameters that are typically reported as "Total" may vary slightly from the sum of the reported component parameters.

### **ANALYTE QUALIFIERS**

Date: 03/04/2022 02:04 PM

D3 Sample was diluted due to the presence of high levels of non-target analytes or other matrix interference.



# **QUALITY CONTROL DATA CROSS REFERENCE TABLE**

Project: Brunswick GA 2/28/22

Pace Project No.: 20236149

Date: 03/04/2022 02:04 PM

| Lab ID      | Sample ID  | QC Batch Method | QC Batch | Analytical Method | Analytical<br>Batch |
|-------------|------------|-----------------|----------|-------------------|---------------------|
| 20236149001 | Oglethorpe | EPA 3050        | 249087   | EPA 6010          | 249151              |
| 20236149002 | Mall       | EPA 3050        | 249087   | EPA 6010          | 249151              |

| Relinquished by/Company: (Signature)            | Relinquished.bt//Company: (Signature)                                | Reinquisned by Company: (Signature)          |                                    | Packing Ma   | Customer Remarks / Special Conditions / Possible Hazards: Type of Ice Used: |  |  |  | 2-24  | Onlethorpe 2-24 | Customer Sample ID Matrix Grab Composite Start)  Date Time | Comp /                        | * Matrix Codes (Insert in Matrix box below): Drinking Water (DW), Ground Water (GW), Wastewater (WW), Product (P), Soil/Solid (SL), Oil (OL), Wipe (WP), Air (AR), Tissue (TS), Bioassay (B), Vapor (V), Other (OT) | ∺ ≤       | Sample Disposal: Rush:   Rush:  | Collected By (signature): Turnaround Date Required: | Collected By (print): Purchase Order #: Quote #:                  | Phone: 2519 92-5911 Site/Facility ID #:                                     | GA '                                | Customer Project Name/Number: State: (                    | Copy To: Site Collecti                     | SOUTH Final To: | roman lochni              | Company: Billing Information: | Pace Analytical Chain-of-Custody is a LEGAL DI                      | CMAIN-OF-CUSTOUT A                           |
|---|--|--|------------------------------------|--|---|--|--|--|-------|-----------------|--|-------------------------------|---|-----------|---------------------------------|---|---|---|-------------------------------------|---|--|-----------------|---------------------------|-------------------------------|---|--|
| Received by/Company: {Signature} Date/Time:     | Received by/Company: (Signature)                                     | 11 2 Received phytoppany, Josephynes 2/28/22 | s) screened (<500 cpm): Y N NA Sam | Packing Material Used:                               | Wet Blue Dry Non  |  |  |  | M; 65 | /b: 30 X        | Date Time CI Ctns  | ed (or Composite End Res # of |   | Analysis: | Field Filtered (if applicable): | Immediately Packed on Ice:                          | DW PWS ID #: DW Location Code:                                    | Compliance Monitoring? [ ] Yes  |                                     | County/City: Time Zone Collected: An                      | (6) methanol, (7) sodium bisulf.           | chia to cam     | Container Preservative Ty | 1                             | Chain-of-Custody is a LEGAL DOCUMENT - Complete all relevent fields | CHAIN-OF-COSTODY Analytical Request Document |
| PIM: Non Conformance(s): Page: PB: YES / NO of: | Template: Trip Blank Received: Y N (MS) Prelogin: HCL MeOH TSP Other | 14/2 Table #:                                | Ciem Co                            | 2581234 Therm ID#: 18 Cooler 1 Temp Upon Receipt 28. | Y (N) N/A Lab Sample Temperature Info                                       |  |  |  |       |                 |  | Lab Sample # / Comments:      | Lan USE ONLY:   |           | 14                              | andspace Acceptable yulated Soils                   | Correct Bottles  Sufficient Volume  Samples Received on Ice  Y(N) | Custody Signatures Present NA Collector Signature Present NA Bottles Intact | Custody Seals Present/Intact Y W NA | Analyses Lab Profile/Line:  Lab Sample Receipt Checklist: | triosurate, 19) hexane<br>erved, (O) Other | 20236149        |                           |                               | LIO#: 20236149  |  |