#2106 DUNBAR CREEK WPCF REHAB (IN PROGRESS - TBD)







- 1. Post-Hurricane Helene Inspection: A large oak tree fell at the back entrance, and staff used heavy equipment to remove it. And Post Hurricane Milton inspection no site issues or damage to report.
- 2. View of the large oak tree that fell at the back entrance removed from blocking service access to the plant.
- 3. View of the newly installed Scum Pump Station next to the new clarifier splitter box in the background.