



Ray Juliano
2909 Newcastle St
Brunswick Georgia
Tel: 912-261-7149
Fax: 912-261-7172
E-mail: rjuliano@bgjwsc.org

Inspection photos

City : Brunswick	Street : 111 F Street	Date : 4/30/2018	Pipe Segment Reference : 40320280+40320270	Section No : 1
---------------------	--------------------------	---------------------	---	-------------------




Photo: 40320280_40320270_02052018_134435_A.jpg, VCR No.: 1
281.9FT, Joint Offset Medium




Photo: 40320280_40320270_30042018_104417_A.JPG, VCR No.: 1
292.2FT, Broken Soil Visible, from 08 to 08 o'clock, within 8 inches of joint: YES