

## Facility Construction Project Photos – April 2022

#906 WATER POLLUTION CONTROL REHAB- ACADEMY CREEK WPCF (80% - MARCH 2022)



1. White Electrical Construction working on Sludge Unloading System at the Sludge Drying Building.
2. Disc cloth filtration working effectively to remove settleable solids, foam and floatable scum.
3. Ongoing Baffle Curtain and Feed Well construction activities at Clarifier No. 5.
4. Newly installed prefabricated aluminum truss bridge between Main Flow Splitter and MCC building
5. Ongoing demolition activities in the grit screening area at the Headworks.
6. Jeff Henderson (GMC Construction Inspector) performing site inspection at the Headworks.