

Facility Construction Project Photos – August 2022

#2021 GALVANIZED REPLACEMENTS- SYSTEM-WIDE (SELF-PERFORMED) (IN PROGRESS-FISCAL YEAR)



1. Alvin Hall (WDD Supervisor) and Water Distribution Department Crew Members proudly showcase 2-inch galvanized waterline, broken flange, and gate valve removed from 1300 Downing Street on SSI.
2. Close-up view of the broken flange removed from 1300 Downing Street.
3. Close-up view of 2-inch galvanized waterline removed from 1300 Downing Street.