

Facility Construction Project Photos – August 2022

#702 (PHASE III) NMSI PHIII FORCEMAIN RE-ROUTE (99% - AUGUST 2022)



1. Mike Fields (JWSC Senior Inspector) and Linda White (Southern Landing HOA President) are excited to discuss the remaining final sidewalk and site restoration punch list activities for the entrance of the Southern Landing neighborhood.
2. Contractor installing additional tracer wire access boxes that allow proper locating of wire without loss or deterioration of low-frequency signal.
3. Contractor demolishing existing sidewalk broken concrete and forming underway for pouring and finishing.