


## Facility Construction Project Photos – December 2022

2203 EST REHAB AT GLYNN PLACE MALL AND OGLETHORPE SITES (2% - JUNE 2023)



1. Drone view of the Glynn Mall Place EST – The welding Contractor is installing containment clips to the roof knuckle in preparation for the blasting and painting containment outriggers system.
2. Drone view of the Oglethorpe EST – the top view of the communication corral system on top of the tank. An onsite meeting with AT&T, Utility Services, and the construction team is scheduled for 12/27/2022 to discuss the sector-by-sector shutdown of the communication system for the proposed work.