

Facility Construction Project Photos – September 2022

#2021 GALVANIZED REPLACEMENTS- SYSTEM-WIDE (SELF-PERFORMED) (IN PROGRESS-FISCAL YEAR)



1. Water Distribution Department Crew Members addressing the 1-inch galvanized service waterline failure at the intersection of Fourth Avenue and Norwich Street.
2. Alvin Hall (WDD Supervisor) is providing project updates and public education about the JWSC Galvanized Replacement Program to a nearby Resident.
3. Close-up view of 1-inch galvanized waterline removed from the intersection of Fourth Avenue and Norwich Street.