

Facility Construction Project Photos – February 2023

#2021 GALVANIZED REPLACEMENTS- SYSTEM-WIDE (SELF-PERFORMED) (IN PROGRESS-FISCAL YEAR)



1. 1-inch galvanized valve removed from 3900 Hill Street in the North Mainland District.
2. Steven Fones (WDD Crew Leader) and Joseph Bartlett assisting the UWS Crew Members in repairing a 1-inch galvanized water service line at 3900 Hill Street.
3. 2-inch galvanized fitting removed from 159 Pierce Butler Drive in Saint Simons Island District