

Facility Construction Project Photos – January 2023

2203 EST REHAB AT GLYNN PLACE MALL AND OGLETHORPE SITES (3% - JUNE 2023)



1. Drone view of the Glynn Mall Place EST – The Contractor is preparing the outrigger containment system to erect a tent-like curtain structure to contain sandblast media, paint overspray, and other debris associated with sandblasting and painting during the rehabilitation process.
2. Interior view of the existing piping and valve assemblies inside the pedestal base in the Oglethorpe EST.