


Facility Construction Project Photos – January 2023

#2021 GALVANIZED REPLACEMENTS- SYSTEM-WIDE (SELF-PERFORMED) (IN PROGRESS-FISCAL YEAR)



1. Janice Meridith (Executive Commission Administrator) inspecting a 1-inch galvanized valve removed from 1032 Beachview Drive in the Saint Simons Island District.
2. Alvin Hall (WDD Supervisor) showcasing to the PCD Staff a colossal 2-inch galvanized line, tee, and isolation valves removed from 515 North Windward, Unit 200 in the Saint Simons Island District.