


Facility Construction Project Photos – June 2023

#2021 GALVANIZED REPLACEMENTS- SYSTEM-WIDE (SELF-PERFORMED) (IN PROGRESS-FISCAL YEAR)



1. Alvin Hall (WDD Supervisor) showcasing to Tim Cheek (PCD Planning Review Coordinator) a failed 2-inch galvanized line with fitting removed from the Union Street and 2ND Avenue intersection in the City of Brunswick District.
2. Zachary Deen (WDD Crew Member) showcasing a 2-inch galvanized segment connected to a saddle clamp and gate valve removed from the City of Brunswick District.
3. A 1-inch galvanized line segment was removed from Saint Simons Island District.