

## Facility Construction Project Photos – March 2023

#2021 GALVANIZED REPLACEMENTS- SYSTEM-WIDE (SELF-PERFORMED) (IN PROGRESS-FISCAL YEAR)



1. Nearby resident of Prior Avenue inspecting the 1-inch galvanized lines removed from 216 and 217 Prior Avenue in the North Mainland District. The residents said they recognized and appreciated the hard work that the JWSC staff put forth in this repair for the galvanized replacement.
2. A closeup section view of the 1-inch galvanized line removed from 216 and 217 Prior Avenue.
3. A variety of 2-inch galvanized fittings removed from 407 Greer Drive in the City of Brunswick District.