

Facility Construction Project Photos – May 2023

#2021 GALVANIZED REPLACEMENTS- SYSTEM-WIDE (SELF-PERFORMED) (IN PROGRESS-FISCAL YEAR)



1. Alvin Hall (WDD Supervisor) showcasing a failed 2-inch galvanized line with fitting removed from the Live Oak Fiber Installation Project at 116 Paradise Marsh Circle in the North Mainland District.
2. Patrick Limano (WDD Crew Leader) showcasing a 1-inch galvanized line removed from 711 Albany Street in the City of Brunswick District.
3. A 2-inch galvanized line with a gate valve was removed from Saint Simons Island District.