

Facility Construction Project Photos – June 2024

#2207 WESLEY OAKS CIRCLE WATERMAIN IMPROVEMENTS (70% - JUNE 2024)



1. Close-up view of the 2-inch galvanized removed and 8-inch cut-out HDPE section installed at the Wesley Oak Circle Project.
2. Mrs. Eva Taylor (514 Wesley Oak Resident) inspects the 2-inch galvanized line with fitting and an 8-inch HDPE section. She appreciates the work and is excited about waterline improvements.
3. Newly installed fire hydrant assembly at 507 Wesley Oak Circle.