

Facility Construction Project Photos – February 2024

#2021 GALVANIZED REPLACEMENTS - SYSTEM-WIDE (SELF-PERFORMED) (IN PROGRESS-FISCAL YEAR)



1. Alvin Hall (WDD Supervisor) showcases a 1-inch galvanized line and fittings removed from East 3rd Street in the City of Brunswick District. A utility boring contractor hit the water line and twisted the service connection, causing it to break loose.
2. A newly shipped HDPE pipe stored at the WDD South Harrington office is awaiting the HDD contractor to schedule installation for Menendez Avenue & Wesley Oak Circle in the Saint Simons Island District.