Facility Construction Project Photos - June 2024







- 1. The existing well pump, motor, column, and pump head were removed for inspection and repair.
- 2. Woodrow Sapp Crew member (Reeves Young Subcontractor) preparing well column impeller disassembly for transportation and inspection
- 3. Northbound view of the existing Canal Water Production Facility ongoing demolition activities and site grading.
- 4. Bruce Broome (RY Senior Superintendent), Jesse Williamson (RY On-Site Superintendent), and Jake Watson (RY Project Engineer) are observing land clearing activities performed for the new ground storage tank location.
- 5. Southeast-bound view of the back side of the existing Canal Water Production Facility ongoing demolition activities and site grading.