

Facility Construction Project Photos – February 2025

#2104 PUMP STATION 4002 REHAB (IN PROGRESS - TBD)



Facility Construction Project Photos – February 2025



Facility Construction Project Photos – February 2025



1. Jay Boudreaux (Pump and Process) and the construction team inspecting the wiring for pump disconnects in preparation for station startup testing.
2. David Grantham (JWSC Assistant Director) inspecting ATS panel in preparation for startup testing.
3. PopCo crew members rerouting HVAC unit condensation line around pump disconnects.
4. View of the construction activities in the instrumentation and control room.
5. View of the dry pit – both high-service pumps are working with no issues to report.
6. Drone Northbound view of the ongoing construction activities at the project site.