

Facility Construction Project Photos – January 2025



1. Northbound view of ongoing steel reinforcement construction activities at the UV channel structure.
2. Alexis Rodriguez (RY Foreman) showcases the Trojan UV system stored at the Sludge Drying building - the inventory has been inspected and accounted for.
3. Alexis showcasing the newly installed conduits & junction box at the dewatering control room.
4. 10 RAS pumps were delivered and stored at the RY laydown yard.
5. RAS piping and fitting are preliminary prep for assembly at the RY laydown yard.
6. David Grantham (JWSC Assistant Director of WW Maintenance) reviewing the Academy Drawings.
7. Brandon Horton (RY Operator) showcasing a 48-inch butterfly valve.
8. RY Crew member installing 8-inch isolation valve next to the Southside of the Contact Chamber.