

Facility Construction Project Photos – January 2025



1. Westbound view of the project site—The GA Power pole has been relocated to the outside of the fencing, and power underground wiring and a meter have been installed.
2. Northbound view of the project site – generator disconnect panel installation pending delivery.
3. Southbound view of the project site – stairway handrails pending fabrication and installation.
4. View of the newly installed electrical disconnects for the wall-mounted outdoor condensers.
5. Electrical installation activities are ongoing in the instrumentation and control room.
6. Electrical installation activities are ongoing in the main floor room (loading dock area).
7. View of the dry pit – electrical fixtures and lighting installation completed.