

Facility Construction Project Photos – January 2025



1. Northeast-bound view of the ongoing construction activities – well piping assembly underway.
2. Southbound view of the ongoing construction activities in pump room – preparing wall for painting.
3. Chad Owens (Reeves Young Foreman) is inspecting ongoing electrical work in the control room.
4. View of building service 20-ft grounding rod locations connected to the middle circuit breaker panel.