

## **Facility Construction Project Photos – August 2022**

**2106 DUNBAR CREEK WPCF REHAB (IN PROGRESS-TBD)**



1. Drone overview of the ongoing construction activities at the Dunbar Treatment Plant.
2. View of exterior Aeration Basin No. 2 (AB#2) door access welding repair and final painting.
3. View of interior AB#2 door access welding repair and final painting.
4. View of exterior AB#2 stairway and final painting.
5. View of exterior AB#2 wall and piping final painting.