

Facility Construction Project Photos – October 2022

2106 DUNBAR CREEK WPCF REHAB (IN PROGRESS-TBD)



1. Wetland surveying activities are underway for the Dunbar Construction/Service Entrance.
2. Survey ribbon delineating wetland boundary limits for the Dunbar Construction/Service Entrance.
3. Existing UV Channels & Post Aeration structures to be demolished & replaced with the new system.
4. Future Odor Control tower to be installed beside existing Grit Chamber Structure and Mech. Screen.