

Facility Construction Project Photos – September 2022

2106 DUNBAR CREEK WPCF REHAB (IN PROGRESS-TBD)



1. Drone overhead view of ongoing construction activities between Wet Wells #2WTP1630 and #2WTP1730 – BRW Construction Group, LLC (Contractor) addressing 30-inch pipe collapse.
2. View of 30-inch deteriorated DIP sewer line removed between Wet Wells #2WTP1630 and #2WTP1730 – the final site restoration of pipe collapse pending delivery of roadway material.