

## Facility Construction Project Photos – April 2023

2106 DUNBAR CREEK WPCF REHAB (IN PROGRESS-TBD)



1. The Dunbar Trojan UV system was unexpectedly delivered to the plant a month early.
2. Drone view of the demolition activities at the post-aeration structure.
3. View of the wall-cutting activities at the post-aeration being performed by Hardcore Concrete Co.
4. Mark Whitlow (WWTD Onsite Operator) is checking the reinforcement bars for the new odor control tower pad.
5. BRW Crew Member cross-checking inventory with shipping manifesto of newly delivered structural rebar.