

## **Facility Construction Project Photos – December 2023**



1. Roofing installation is in progress, and system startup is anticipated for the Post-Aeration Basin by the end of the month.
2. BRW Crew Members perform final installation checks on the AquaDisk Cloth Media Filter components and Trojan UV wiring system at the Post-Aeration Basin.
3. Trojan Start-up Tech (Wharton-Smith, Inc.) inspecting the Trojan UV wiring system.
4. Drone view of the sediment debris activities from Aeration Basin #1 in preparation for bubbler system upgrades similar to the recently upgraded Aeration Basin #2.
5. Drone view of the future location of the third clarifier.
6. Drone overview of the ongoing construction activities at Dunbar.