

## **Facility Construction Project Photos – February 2023**

**2106 DUNBAR CREEK WPCF REHAB (IN PROGRESS-TBD)**



- 1. Drone view of the ongoing construction activities at the Aeration Basin #2 at the Dunbar Creek Treatment Plant.**
- 2. Contractor team member (BRW Construction Group) installing new airline piping in connection to the new aeration diffuser, which is anticipated to be delivered by the end of the month.**
- 3. Contractor team member (BRW Construction Group) installing new RAS for the Aeration Basin #2.**