

Facility Construction Project Photos – March 2023

2106 DUNBAR CREEK WPCF REHAB (IN PROGRESS-TBD)



1. Drone view of the contractor mobilizing additional bypass equipment to address sinkhole forming due to a failed 30-inch DIP sewer pipe connecting the grit chamber to a wetwell near the RAS bldg.
2. View of failed 30-inch DIP sewer pipe section removed.
3. The contractor is removing the existing sewer pipe, replacing it with new 30-inch PVC piping, and installing new manhole access points along the alignment.
4. Drone view of the ongoing 30-inch sewer replacement activities.