

## **Facility Construction Project Photos – May 2023**

**2106 DUNBAR CREEK WPCF REHAB (IN PROGRESS-TBD)**



1. Drone Southbound overview of the project site.
2. Drone Eastbound view of Aeration Basin #2 diffuser piping installation is underway.
3. Drone Westbound view of Concrete and structural reinforcement forming at the Post-Aeration Basin.
4. Subcontractor performing pavement removal in preparation for electrical conduit installation.