

## **Facility Construction Project Photos – February 2024**



1. Drone view of the ongoing construction activities – the old UV Channel and disk filter systems have been removed and lines terminated. New Post Aeration basin punchlist inspection is scheduled.
2. Drone view of ground excavation and dewatering activities for the third clarifier location.
3. As expected, The Trojan UVSigna water treatment system works successfully by delivering consistent performance at the new post-aeration basin structure.
4. The Aqua-Aerobic System cloth media filtration system is in service and working effectively.
5. Aeration Basin #1 with the center mixer installed and online with no issues to report.