

Facility Construction Project Photos – September 2024



1. Drone view of the ongoing construction activities at the Dunbar Creek Treatment Plan.
2. Drone view of the clarifiers – BRW crew members are working on final adjustments to the scum trough and effluent trough at Clarifier #3.
3. View of the 30-inch piping connected underneath the new splitter box.
4. View of the final wall coating resurfacing activities underway at the Post-Aeration Basin.