

Facility Construction Project Photos – December 2023

#2105 PUMPSTATION 4044 REHAB (1%-OCTOBER 2024)



1. Westbound view of Pump Station 4044 construction activities – heavy construction equipment was mobilized to the site, and a 30-inch tree was removed for the wet well installation.
2. Southbound view of the existing sanitary sewer manhole# 40210250 on Altama Connector – Contractor to connect, rehabilitate, and coat the existing manhole.