

Facility Construction Project Photos – August 2026

#2216S SPLOST EXIT 29 – DIV I WATER PRODUCTION FACILITY (IN PROGRESS – AUGUST 2026)



Facility Construction Project Photos – August 2026



Facility Construction Project Photos – August 2026



1. Westbound overview of the ongoing construction activities at the project site.
2. Northbound drone view of the ongoing construction activities at the well motor & piping assembly.
3. Design & Construction team inspecting the access port for the CL2 injection valves to the GST.
4. Design & Construction team discussing progress and remaining items in the high service pump room.
5. T&H Design & Construction team is inspecting the covered 12-inch WL at the front service gate.
6. Keith Strong (T&H Senior Field Representative) is inspecting the tubing connection in the CHEM RM.