

Facility Construction Project Photos – March 2026

#2216S SPLOST EXIT 29 - DIV III WATER LOOPS (IN PROGRESS – FEBRUARY 2026)



Facility Construction Project Photos – March 2026



1. JWSC Leadership Academy is visiting preliminary pressure testing preparation for the waterline connection in front of the Southwind Drive Subdivision.
2. Keith Strong (T&H Senior Field Representative) is conducting turbidity testing at Southwind Drive.
3. RY Crewmember is performing safety fencing inspection and repair at the Cinder Hill Drive Segment.
4. RY Crew is preparing for an 8-inch HDPE WL connection at Barrington Oaks Subdivision.