

Facility Construction Project Photos – May 2026

#2216S SPLOST EXIT 29 - DIV III WATER LOOPS (IN PROGRESS – MAY 2026)



Facility Construction Project Photos – May 2026



1. Construction team performing routine inspection for the installed 8-inch WL at 187 Cinder Hill Drive.
2. Construction team performing routine inspection for the installed 8-inch WL at 150 Bartram Trail.
3. T&H team members perform routine inspection for the installed 8-inch WL at Barrington Oaks.
4. RY Crewmember is performing routine seeding and watering to optimize soil water absorption to establish grass growth.