

Facility Construction Project Photos – September 2026

#2213 EXIT 42 ELEVATED STORAGE TANK (IN PROGRESS – MARCH 2027)



Facility Construction Project Photos – September 2026



Facility Construction Project Photos – September 2026



Facility Construction Project Photos – September 2026



- 1. Mixon One Construction (Phoenix subcontractor) superintendent and foreman are observing waterline installation and site grading activities.**
- 2. Mixon crew members working on 16-inch waterline installation**
- 3. Interior view of the ongoing interior piping and fitting assembly from the access doorway.**
- 4. Interior view of the ongoing interior piping and fitting assembly from the garage doorway.**
- 5. Drone overview of the ongoing construction activities at the project site.**
- 6. Southbound view of the ongoing construction activities at the project site.**
- 7. Drone overview of the waterline installation activities.**
- 8. Drone overview of the waterline tie-in connection point at the project site.**